



CASE STUDY



CAT® 777E
TRUCK BODY TAIL

PROBLEM:

The company was experiencing excessive downtime, providing maintenance on their CAT® 777E haulers. They were installing AR500 30mm liners, which needed maintenance interventions every 1,200 Hours.

CHROMEWELD™ 600 DELIVERS...

- **7X LONGER WEAR LIFE**
- **33% LIGHTER WEIGHT** Over standard AR500 liners



WHO: LARGE MINING COMPANY

WHAT: CAT® 777E TRUCK BODY TAIL

WHERE: NORTHERN CAPE, SOUTH AFRICA

INDUSTRY: MINING

CHALLENGE: HIGH ABRASION

SOLUTION: CHROMEWELD 600



CHALLENGE:

High Abrasive Wear on Tail

- Currently using AR500 30mm liners
- Maintenance Interventions Every 1,200 Hours

INSTALLATION:

Date of CHROMEWELD 600 Installation

- October 14, 2022


SOLUTION:

Reduce Abrasion on Tail

- Install CHROMEWELD 600 - 10mm on 10mm

DATA:

PROJECTED HOURS UNTIL 100% WORN



RESULTS:

CHROMEWELD™ 600 DELIVERS...

- **7X LONGER WEAR LIFE**
- **33% LIGHTER WEIGHT**

Over standard AR500

GET A QUOTE

- +1 724.452.5252
- sales@jadcomfg.com
- www.jadcomfg.com

CONTACT US

- JADCO Manufacturing Inc.
- 167 Evergreen Road
- Harmony, Pennsylvania 16037

MADE IN USA

